



101 734 275

CJC

Docket No.: M4065.0383/P383-B
(PATENT)

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Letters Patent of:
Kie Y. Ahn et al.

Patent No.: 7,064,438

Issued: June 20, 2006

For: LOW-LOSS COPLANAR WAVEGUIDES

REQUEST FOR CERTIFICATE OF CORRECTION
PURSUANT TO 37 CFR 1.322

Attention: Certificate of Correction Branch
Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Certificate
AUG 24 2006
of Correction

Dear Sir:

Upon reviewing the above-identified patent, Patentees noted errors which should be corrected.

In the Specification, the PTO made the following error to be corrected:

Column 1, line 49, "usefull" should read --useful--.

In the Claims, the PTO made the following error to be corrected:

Claim 3, column 6, line 49, "ground Angstroms" should read --ground conductor planes and signal conduction line have a thickness of about 100,000 Angstroms--.


AUG 25 2006

The errors were not in the application as filed or amended by applicant;
accordingly no fee is required.

Transmitted herewith is a proposed Certificate of Correction effecting such
amendment. Patentees respectfully solicit the granting of the requested Certificate of
Correction.

Dated: August 22, 2006

Respectfully submitted,

By 

Thomas J. D'Amico

Registration No.: 28,371

Elizabeth Parsons

Registration No.: 52,499

DICKSTEIN SHAPIRO LLP

1825 Eye Street, NW

Washington, DC 20006-5403

(202) 420-2200

Attorneys for Applicants

AUG 25 2006

**UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION**

Page 1 of 1

PATENT NO. : 7,064,438
APPLICATION NO. : 10/734,275
ISSUE DATE : June 20, 2006
INVENTORS : Kie Y. Ahn et al.

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In the Specification, the following error is corrected:

Column 1, line 49, "usefull" should read --useful--.

In the Claims, the following error is corrected:

Claim 3, column 6, line 49, "ground Angstroms" should read --ground conductor planes and signal conduction line have a thickness of about 100,000 Angstroms--.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Thomas J. D'Amico
DICKSTEIN SHAPIRO LLP
1825 Eye Street, NW
Washington, DC 20006-5403

1

AUG 25 2006